

FMR Hardcoated Lexan® Polycarbonate VStream® Windscreen for Kawasaki® Versys-X 300 N20124; Low Dark Tint N20125; Mid Light Tint N20126; Tall Clear



Thank you for purchasing a National Cycle product. Read these instructions carefully and thoroughly before beginning work. Dealers, if installing this windscreen for a customer, please give them this manual upon completion. It contains information needed to properly maintain and use this product.



# Attention:

Special notes and cautionary measures which can prevent damage to the accessory or motorcycle.




Tips for facilitation of operation, control and adjustment, as well as maintenance work.

# CONTENTS OF KIT


Item	Description	Part No.	Qty.
(1)	VStream® Windscreen		1
Bag#1291			
(2)	Spacer, Black	44-443545-000	4

TOOLS REQUIRED 5mm Allen Wrench





(1)



## PREPARATION

1. Position motorcycle securely on its center stand. Remove the OEM windscreen, four screws, and four bushings. Hardware will be re-used. (5mm Allen Wrench) Figure 1


### INSTALLATION


1. Install OEM bushing around the windshield mount hole on motorcycle. *Figure 2* 

Figure 2









2. Install the VStream Windshield using the OEM Screw and the Black Spacer (2) from Bag#1291. Tighten the 4 Screws firmly. (5mm Allen Wrench) Figure 3

Figure 3

National Cycle, Inc. PO Box 158 Maywood, IL 60153-0158 USA 708-343-0400 / Fax: 708-343-0625 / www.nationalcycle.com / info@nationalcycle.com



Ask for Shield Wash™ and RainZip® at your local dealer or visit www.nationalcycle.com.

#### **CLEANING AND MAINTENANCE**

To clean the screen, wash with a clean soft cloth and plenty of warm water and, if necessary, a non-abrasive soap such as dishwashing liquid. Flannel or soft chamois make good cleaning cloths. **Paint, glue residue or grease removal:** Moisten cotton wad with naphtha or turpentine followed by a wash as above.

National Cycle **Shield Wash™** (N1401-01) makes a good daily cleaner and comes with a handy travel-size bottle. Shield Wash is safe for all windshields and helmet visors.

Do not clean polycarbonate in hot sun or high temperatures. Do not clean the screen with household glass cleaners.

Do not allow brake fluid, alcohol, or strong solvents to contact the screen.

#### RAIN REPELLENT

Do not use rain protective products made for glass. We recommend National Cycle's **RainZip**® (N1410-01) to keep your windscreen clear in rainy weather.

VStream® Windscreen Patent no. 7,387,328



#### Register Your Windshield Online at www.nationalcycle.com

#### National Cycle 3-Year Limited Warranty

National Cycle hereby warrants to the original registered owner of a National Cycle polycarbonate windshield for a period of three years from the date of purchase against breakage. This limited warranty is expressly limited to the replacement of the polycarbonate windscreen. This limited warranty does not include scratches, coating failure, cosmetic wear and tear, replacement of hardware, or any consequential damages or expenses including labor cost of installation, removal and/or replacement, inconvenience, inbound freight expenses or damage to any other component of the motorcycle or any other accessories. Certain chemicals, generally known as acidic hydrocarbons, are known to cause polycarbonate damage and will not be covered under this limited warranty. Please refer to the cleaning instructions supplied with all National Cycle windshields.

Visit www.nationalcycle.com for further details or call or write National Cycle

# WARNING

Never ride your motorcycle with loose accessory mounting hardware. Check the hardware for tightness regularly.

Today's motorcycles are built with enough frame rigidity to withstand the moderate loads imposed on them by the foreseeable addition of an accessory(ies). If an accessory(ies) adversely affects your motorcycle's stability, immediately remove the accessory(ies). Do not ride a motorcycle that exhibits unsafe handling traits.

Have experienced service personnel correct any problem before riding with the accessory(ies) installed. For further questions concerning handling problems associated with an accessory(ies), contact your dealer, motorcycle manufacturer, or accessory manufacturer.

Sunlight reflected off the inside curvature of the windscreen can, at certain times of the day, cause extreme heat buildup on the motorcycle's instruments and possibly even melt them. Exercise care in parking to avoid this. Park your motorcycle facing the sun, or place an opaque object over the instruments and dash panel.