Thank you for purchasing a ZTechnik® product. Please read these instructions carefully and thoroughly before beginning work. Dealers if installing this windshield for a customer please give them this manual. It contains information needed to properly maintain and use this product.



Attention

Special notes and cautionary measures which can prevent damage to the accessory or motorcycle.



Tips for facilitation of operation, control and adjustment, as well as maintenance work.



T-25 Torx Wrench

PARTS LIST

Index Description

VStream Windshield, Hardcoated Lexan® polycarbonate

Qty.

INSTALLATION

Retain all fasteners, as they will be reused.

- 1. Remove the screws that hold the stock windscreen in place. Store stock windscreen, it will not be reused. (T-25 Trox)
- 2. Place your VStream Windscreen into position and install to motorcycle using the original hardware.
- 3. Tighten the screws firmly. Do not over tighten. (T-25 Trox)

View other ZTechnik® Products for your Motorcycle at: www.ZTechnik.com

CHAIN GUARD . TIRE HUGGER



MAINTENANCE

To clean the screen, wash with a clean soft cloth, plenty of warm water and if necessary, a non-abrasive soap such as dishwashing liquid. Flannel or soft chamois make good cleaning cloths. Paint, glue residue or grease removal: Moisten cotton with Naphtha or Turpentine followed by a wash as above. National Cycle Shield Wash™ makes a good daily cleaner and comes with a handy travel size bottle. N1401-01 Shield Wash is safe to use on helmet visors as well.

Do not allow brake fluid, alcohol, or strong solvents to contact the screen.

ZTechnik 3-Year Limited Warranty Register your windshield on Line at: www.ZTechnik.com

ZTechnik hereby warrants to the original registered owner of a ZTechnik polycarbonate windshield for a period of three years from the date of purchase against breakage. This limited warranty is expressly limited to the replacement of the polycarbonate windscreen. This limited warranty does not include scratches, coating failure, cosmetic wear and tear, replacement of hardware, or any consequential damages or expenses including labor cost of installation, removal and/or replacement, inconvenience, inbound freight expenses or damage to any other component of

the motorcycle or any other accessories. Certain chemicals, generally known as acidic hydrocarbons, are known to cause polycarbonate damage and will not be covered under this limited warranty. Please refer to the cleaning instructions supplied with all ZTechnik windshields.

Visit www.ZTechnik.com for further details are call or write ZTechnik / PO Box 158 / Maywood, IL 60153 / 708-343-0400

VStream® windshield patent no. 7,387,328

ZTechnik PO Box Maywood, IL 60153-0158 USA

708-343-0400 / Fax: 708-343-0625 / www.ZTechnik.com / e mail: info@ZTechnik.com

©2011 National Cycle, Inc.

Page 1 of 1

10-118581-000 05/11